

Hallgrímskirkja Church, interior renovations

Description:

All benches were removed for preparation of paint work. Pulpit and organ had to be specially protected. Tiled floors were covered with plastic and plywood.

Door openings cut in side walls for emergency exits to meet the fire code.

Interior paint, total of some 5000 m².

Finishes for a new main door, which is a bronze and mosaic sculpture by Leifur Breiðfjörð. Installation was done by the manufacturer's employees.

**Client:**

Hallgrímskirkja parish.

Duration:

January 2010 – February 2010

Architects:**Civil design:**

Verkís.

Ístak's work:

Main contractor

**Address:**

ÍSTAK hf.
Engjateigur 7
105, Reykjavík, Iceland

Tel: +354 530 27 00

Fax: +354 530 27 24

e-mail: istak@istak.is

Web site: www.istak.is